	CERCLA REMOVAL ACT	ION DAILY WORK ORDER		
	DAILY WORK ORDER			
RESPONSE LOCATION		CONTRACT NO.	ORDER NO.	
(SITE NAME AND/OR				
ADDRESS AND ZIP CODE)			1	
,,		68-S6-2101	0028	
Meadowlands Plating Facility		DATE 11 June	SHIFT	
890 Paterson Plank Road		Drite	19	
East Rutherford, NJ 07073			1	
		1999		
SITE/SPILL NO.	EPA REGION	ON-SCENE COORDINATOR		
LW		Mike Solecki		
	[2			
CONTRACTOR		CONTRACTOR RESPONSE MANAGER		
Earth Tech, Inc.		Kevin Shaver		
	MONI	<u>. </u>		
MONITOR(S)				
	DESCRIPTION OF MA			
	DESCRIPTION OF WO	RK TO BE PERFORMED		
	Transportation and Disposal of	f water treatment sludges upon	waste acceptance approval.	
<u> </u>	Clean storage tank 3.	· · · · · · · · · · · · · · · · · · ·	The second secon	
	Complete the cleaning of office	2 04000		
		e areas.		
	Demobe storage tank 2.			
	Demobe box truck and equipm	nent upon completion.		
				
· · · · · · · · · · · · · · · · · · ·				
	NUMBER OF PERSO	ONNEL AUTHORIZED		
SUPERVISORS		OREMAN	OPERATORS	
	 -	UREIVIAIN	OFERATORO	
LABORERS		OTHER (SPECIFY): PCT, Cher	mist T&D Coordinator (off-site)	
				
\	EQUIPMENT AND EXPENDAE			
ITEM	QUANTITY	ITEM	QUANITITY	
Backhoe	1	Laptop computer	3	
Forklift	1	Printer	2	
Exp./O2 monitor			- 4	
	1	Fax machine	<u> </u>	
Handheld radio	6	Air compressor	11	
Truck	3	Pressure washer	2	
In-line bag filter	2	Double diaphram pump	2	
Copy machine	1 1	Submersible pump	3	
Оору внасинна	1	Subinciainic bamb		
I CERTIFY THAT THE ABOVE	F WORK IS ORDERED AND	T	***************************************	
AUTHORIZED BY THE CONT				
PERFORMANCE OF THE AB		I ACKNOWLEDGE RECEI	PT OF THIS WORK ORDER.	
	OVE CITED DELIVERY		· · · · · · · · · · · · · · · · · · ·	
ORDER.		l ,		
SIGNATURE OF OSC		SIGNATURE OF CONTRACT	TODIS DEDDESENTATIVE	
Y /		11/6 -\1	IORO REPREDENTATIVE	
Muliar		I ham I to them		
	ASTRONAUNITO (INICI LIDE TIME		- 0	
	MENDMENTS (INCLUDE TIME		ON)	
Equipment Operate	or and Chemist	demobed		
			Z	
			443111	
			THE PER PER PER PER PER PER PER PER PER PE	
CIDNIA THE OF OCC		SIGNATURE OF CONTRACT	TODIO DEDDECENTATIVE	
SIGNATURE OF OSC				
/		Kin Xl Vary		

.

	CERCLA REMOVAL ACT	ION DAILY WORK ORDER		
	DAILY WORK ORDER			
RESPONSE LOCATION		CONTRACT NO.	ORDER NO.	
(SITE NAME AND/OR				
ADDRESS AND ZIP CODE)		68-S6-2101	0028	
Meadowlands Plating Facility		DATE 11 June	SHIFT	
890 Paterson Plank Road		DATE IT GAILS		
East Rutherford, NJ 07073		1000		
SITE/SPILL NO.	TEDA DECION	1999 ON-SCENE COORDINATOR		
	EPA REGION	- · · · · · · · · · · · · · · ·		
LW CONTRACTOR	2	Mike Solecki		
		CONTRACTOR RESPONSE MANAGER		
Earth Tech, Inc.		Kevin Shaver		
	MONI	TOR(S)		
	DESCRIPTION OF WO	RK TO BE PERFORMED		
	Transportation and Disposal a	f water treatment aludees were	wasta accentanna consoval	
	Clean storage tank 3.	f water treatment sludges upor	waste acceptance approvat.	
· · · · · · · · · · · · · · · · · · ·	Complete the cleaning of office	e areas		
	Demobe storage tank 2.	o drodo,		
Demobe storage tank 2. Demobe box truck and equipment upon completion.				
.it				
	NUMBER OF PERSO	ONNEL AUTHORIZED		
SUPERVISORS		OREMAN	OPERATORS	
2 LABORERS	×	OTHER (SPECIFY): PCT, Che	mist_T&D_Coordinator (off-site)	
	EQUIPMENT AND EXPENDA			
ITEM	QUANTITY	ITEM	QUANITITY	
Backhoe	1	Laptop computer	3	
Forklift	1	Printer	2	
Exp./O2 monitor	1	Fax machine	1	
Handheld radio	6	Air compressor	1	
Truck	3	Pressure washer	2	
In-line bag filter	2	Double diaphram pump	2	
Copy machine	1	Submersible pump	3	
	E WORK IS ORDERED AND			
AUTHORIZED BY THE CONT	•	LACKNOWLEDGE RECE	IPT OF THIS WORK ORDER.	
PERFORMANCE OF THE AB	BOVE CITED DELIVERY			
ORDER.				
SIGNATURE OF OSC		SIGNATURE OF CONTRAC	TOR'S REPRESENTATIVE	
Melute In I day				
/ 7 A	MENDMENTS (INCLUDE TIM	E AND AUTHORIZING PERSO	ON)	
Equipment Operal		demobed		
SIGNATURE OF OSC		SIGNATURE OF CONTRAC	TOR'S REPRESENTATIVE	
1 prus	· · · · · · · · · · · · · · · · · · ·	Kin Xl Day		
* /				